

A WARNING

Standard M8 screws, spacers and lock plate supplied with the standard docking stations with part number 501750 and 503600 will not be strong enough in the event of a collision and could cause injury or death in a crash. You MUST use the M10 (high quality steel) bolts, spacer and lock plate supplied with this kit.

Die Standard M8 Schrauben, Zwischenstücke und Verriegelungsplatte, die mit den Standard Docking Stationen mit Art.nr. 501750 und 503600 geliefert werden, sind im Falle einer Kollision nicht stark genug und können bei einem Unfall zu Verletzungen oder zum Tod führen. Verwenden Sie deshalb UNBEDINGT die M10 Schrauben (hochwertiger Stahl), das Zwischenstück und die Verriegelungsplatte, die mit diesem Adaptionskit geliefert werden.

Les boulons M8 standard, les entretoises et la plaque de verrouillage utilisées avec les stations d'accueil standard avec la réf. 501750 et 503600 ne sont pas assez solides en cas de collision et peuvent entraîner des blessures ou la mort en cas d'accident. Il est donc INDISPENSABLE d'utiliser les boulons M10 (acier de haute qualité), l'entretoise et la plaque de verrouillage qui sont fournies avec ce kit d'adaptation.

	Item	Qty	Drawing no	Description3				Rev n	Rev no	
	1	1	501887	Anchoring Plate for Adaptation Set				01		
	2	2	501758	Spacer 320x75x5				02	02	
	3	5	501895	Special Nut M10			00	00		
	4	1	503349	Spacer 8 mm				01	01	
	5	1	503338	Lock Plate for 10 mm Bolt Screw M10x40 Special Q12.9				01	01	
	6	5	500782					03	03	
		Dimension		Material:			List of spare parts: Weight: 0 kg			
	∇	Chamfer:		Surface treatment:		Measures without tol.: DS/EN 22768-M				
	Latest correction:						Replaced by: Replaces:			
	Date: Issuer: Title:					09-05-2022	SUNRISE Q700F			
						LJ				
	Adaptation	ssæt Dahl D	ocking System for Specia	al M10 bolte			-			
Anpassungskit Dahl Docking System für Special M10 boltzen							Scale: D	rawing no.:	Rev no.:	
	Adaptation Kit Dahl Docking System for Special M10 bolts						501889		04	

REVISION HISTORY								
REV	DESCRIPTION	DATE	APPROVED					
01	Parts List updated	12-01-2023	LJ					
02	503277 removed	19-01-2023	LJ					
03	Note 1 added	13-02-2023	LJ					
04	Warninng Text changed	13-03-2023	LJ					